




Adapter Sleeves

Part No.	Cable Size		Use in Mold for Stranded	Sleeve Dimensions			Box Qty.	Approx. Box Wt. (lbs.)
	Concentric Strand	Solid		O.D	I.D.	Length		
ADPSLV6	#12, 14	#10, 12, 14	#6 Sol.	.156	.111	1.00	25	1/4
ADPSLV4	#7, 8, 10	#6, 8	#4 Str.	.227	.177	1.00	25	1/4
ADPSLV2A	#6	#5	#2 Str.	.292	.198	1.00	25	1/4
ADPSLV2B	#4, 5	#3, 4	#2 Str.	.287	.246	1.00	25	1/4
ADPSLV1	#4	n/a	#1 Str.	.340	.246	1.00	25	1/4
ADPSLV1/0	#2	#1	1/0 Str.	.370	.307	1.00	25	1/4
ADPSLV2/0	#1	1/0	2/0 Str.	.420	.359	1.00	25	1/4
ADPSLV3/0	1/0, #1	2/0	3/0 Str.	.452	.389	1.00	25	1/4
ADPSLV4/0	2/0, 1/0	3/0	4/0 Str.	.524	.437	1.50	25	1/4

DESCRIPTION

- Can be used when welding cables smaller than indicated on mold tag.
- Slide over the cable to adapt smaller size cables to a larger size mold.