






ASSEMBLY



(C)

				PART NO. BJC	
				TINNED BANJO CLAMP	
D	CHANGE TO PRE-TINNED CAP CASTING	040502	EHS	-	
C	ADDED BANJOHUB TO BOM	031301	LAL	-	
B	ADDED TIN TO CAP	022001	LAL	-	
A	ADDED BOM	031300	LAL	-	
LET	REVISION	DATE	BY	-	
TOLERANCES UNLESS NOTED:				DRAWN BY: LAL	
FRACTIONAL +/- 1/64				CHECKED BY:	
.00 +/- .010				DATE: 111497	
.000 +/- .005				HARGER 301 ZIEGLER DRIVE GRAYSLAKE, IL 60030 (847) 548-8700	
				REVISION: D	
				SCALE: FULL	
				SHEET: 1 OF 1	